National Transportation Safety Board NTSB ID: NYC97LA054 Aircraft Registration Number: N922FE FACTUAL REPORT Occurrence Date: 02/14/1997 Most Critical Injury: None AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 0620 COVINGTON ΚY 41048 EST Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Cessna 208B Airplane

Air Medical Transport Flight: No

Sightseeing Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 14, 1997, about 0620 eastern standard time, a Cessna 208B, N922FE, operated by Baron Aviation Service, for Federal Express, struck a utility pole during an instrument approach to the Cincinnati/Northern Kentucky Regional Airport, Covington, Kentucky. The airplane was substantially damaged, and the certificated commercial pilot was not injured. Instrument meteorological conditions prevailed for the cargo flight which departed from Memphis, Tennessee, about 0400. The flight was operated on an Instrument Flight Rules (IFR) flight plan under 14 CFR Part 135.

In the NTSB Pilot/Operator Aircraft Accident Report, the pilot stated:

"...Descent into CVG picked up moderate icing along with turbulence, sleet and snow. Was cleared for ILS 27 @ CVG. After intercepting localizer continued ILS until approximately DH where I acquired runway end strobe lights and descended to land. Somewhere during this descent, felt jolt to aircraft but proceeded with normal landing. Upon shutdown noticed damage to aircraft...."

In a telephone interview, the pilot reported that he thought the jolt was a bird strike. The visibility was better than 1/2 mile, and the cloud base was greater than 200 feet. He did not experience any problems with the airplane.

Examination of the airplane revealed that there was about 192 feet of power line wrapped around the landing gear. The left aileron and wing tip were missing from the airplane.

According to the FAA and airport police, a pole was struck 31 inches from the top, at a height of 27 feet above the ground. The pole was located 4,350 feet from the approach end of runway 27, and about 100 feet left of runway center line. The airplane's wing tip and left aileron were found near the pole. A review of airport facilities revealed that the glide slope for runway 27 was set for a slope of 3 degrees. This glide slope would have an elevation of 290 feet above the ground, at a distance of 4,350 feet from the approach end of the runway.

A check of the air/ground voice tape revealed that the pilot did not report the event to the control tower, and the accident was not reported to airport authorities until 2 hours after it occurred. The FAA and airport operations did not have any problems reported regarding the ILS approach to runway 27, by flights that preceded or followed the accident flight into the airport.

Radar Data from the Covington TRACON revealed that while on the approach, the airplane momentarily stopped descending at 1,900 feet for about 13.8 seconds, and again at 1,500 feet for the same time. The airplane was also observed to level off at 1,000 feet for about 9.2 seconds prior to loss of radar data. Additionally, the descent from 1,500 feet to 1,000 feet took 13.8 seconds, and the last 400 feet occurred in 9.2 seconds.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC97LA054

Occurrence Date: 02/14/1997

AVIATION Occurred				rence Type: Accident									
Landing Facility/Approach In	formation	•					•						
Airport Name		Airport ID:	Airport Ele	vation	Rur	nway Used Runway		ay Length R		Runway Width	h		
CINCINNATI INTL ARPT KC			KCVG	897	Ft. MSI	_ 27	27 100		000		150		
Runway Surface Type: Asphalt						·							
Runway Surface Condition:													
Type Instrument Approach: ILS-co	omplete												
VFR Approach/Landing: None													
Aircraft Information													
Aircraft Manufacturer Cessna			Model 208E	/Series					Serial 208B	Number 0022			
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	Number of Seats: 2 Certified Max Gross Wt. 8750 LBS Number of							er of Eng	nes: 1				
				Engine Manufacturer: Model/Series: P&W PT6A-114						Rated Po 600 HP		:	
- Aircraft Inspection Information													
Type of Last Inspection Date of Last Inspection Time Since Last Inspection Airframe Total Time									e Total Time				
AAIP 01/28/1997 35 Hours 7035 Ho								urs					
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site?													
Owner/Operator Information													
Registered Aircraft Owner Street Address 2892 BUSINESS PARK													
FEDEX CORP			City								Zip Coo	de	
MEMPHIS TN 38118 Street Address													
Operator of Aircraft BOX 518													
BARON AVIATION SERVICE				City VICHY						State MO	Zip Cod 65580	de	
Operator Does Business As: Operator Designator Code: DEMA													
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	: On-demand Air T	Гахі											
Operating Certificate:				Operato	r Certifi	cate:							
Regulation Flight Conducted Unde	r: Part 135: Air Ta	xi & Co	mmuter	-									
Type of Flight Operation Conducted	d: Unknown												
		FACTU	JAL REPO	RT - AVIA	TION						Page 2	2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC97LA054

Occurrence Date: 02/14/1997

	AVIATI	Occurrence										
First Pilot	Information											
Name		City					Date of Birth	Age				
On File On F							ïle			File	On File	29
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On File												
Certificate(s): Flight Instructor; Commercial												
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/0	Glider/LTA: None	е										
Instrument	Rating(s): Airpl	ane										
Instructor F	Rating(s): Airpl	ane Single-	engine; Inst	rument Airp	olane							
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?												
Medical Ce	rt.: Class 1	Medica	al Cert. Status	s: Valid Med	dicalno wa	aivers/lim.		Date of L	ast Me	edical E	xam: 06/20/19	96
		•										
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Night Instrument Actual Simulated				Glider	Lighter Than Air
Total Time		3325	720	2985	340	610	23)	75			
Pilot In Cor	nmand(PIC)	3120	720	2780	330	600	18		60			
Instructor		1735		1735		150	5) :	25			
Last 90 Day		250	250	250		175	3		1			
Last 30 Day		85	85	85		70	2)	+			
Last 24 Ho		6	6	6		' 	alami Darfa	rmod2 N-			noond Dilat? No	
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? No												
Flight Pla	n/Itinerary											
	ht Plan Filed: F	R										
								Time Zone				
MEMPHIS 1							М	MEM		0400		EST
Destination State Airport Identifier												
Same as Accident/Incident Location												
Type of Clearance: IFR												
Type of Air	space: Class	С										
Weather	Information											
Source of	Briefing: Compa	any										
Method of	Briefing:											
				FACTUAL	REPORT -	- AVIATIO	N					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: NYC97LA054

Occurrence Date: 02/14/1997

Occurrence Type: Accident

	FTYBOR			, , , , , , , , , , , , , , , , , , , ,	. , , , ,	71001001							
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevation	n	WOF D	WOF Distance From Accident Site Direction From Acc					n Accident Site	е
CVG	0558			0 Ft.	MSL				0 NM		0 Deg. Mag.		
Sky/Lowes	st Cloud Condition: Unkr	nown					0 Ft	. AGL	Condition of Light: Night/Dark				
Lowest Ceiling: Overcast 7					AGL	Visib	oility:	0.5	SM	Altii	meter:	30.00	"Hg
Temperature: 2 °C Dew Point: 2 °C					Wind	Vind Direction: 200 Density Altitude:							Ft.
Wind Speed: 4 Gusts: Weather Condtions at Accident Site: Instrument Conditions													
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensit	ty of Pre	cipitation:	Unknown				
Restriction	Restrictions to Visibility: Fog												
Type of Pr	ecipitation: Drizzle												
Accident Information													
Aircraft Damage: Aircraft Fire: Aircraft Explosion													
Classification:													
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	ТОТА	_					
First Pi	ilot					1		1					
Second	d Pilot												
Studer	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants												
Other (Crew												
Passer	ngers												
- TOTAL /	ABOARD -					1		1					
Other (Ground	0	C		0			0					
- GRANI	O TOTAL -	0	C	_	0	1		1					
					•			-					

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: NYC97LA054

Occurrence Date: 02/14/1997

Occurrence Type: Accident

Admi			

Investigator-In-Charge (IIC)

ROBERT L. HANCOCK

Additional Persons Participating in This Accident/Incident Investigation:

DAVID STROUD FAA FSDO LOUISVILLE, KY